

WXP80S

If the external flexible cable or cord of this luminaire is damaged, it shall be exclusively replaced by the manufacturer or his service agent or a similar qualified person in order to avoid a hazard.

The light source of this luminaire is not replaceable; when the light source reaches its end of life the whole luminaire shall be replaced





FIG-1




FIG-2-A Concrete




FIG-2-B

Wood board

Please make sure the thickness of the wood board no less than 5mm




FIG-3




FIG-4




FIG-5

